

Performed for Joint Inspection of RWTH system in Govt./Pvt. Schools/colleges in Delhi on NGT direction on 16.11.17 in O.A. No. 217/2016.

1. Name and address of unit: Govt Nirankari Senior Sec school / Boys and Girls /  
 2. Area detail: Sank Nirankari, Near Dhandra, N. Delhi  
 ii) Roof top area: 2420 m<sup>2</sup> approx  
 iii) Paved/road/green area (optional): 7957 m<sup>2</sup> approx  
 iv) Total Plot area: 7957 m<sup>2</sup> approx

3. Date of inspection: 28/2/18

[The status given below is as on inspection date]

S.No.	Govt./Pvt.	RWTH system exist or not	Status of RWTH system, if exist	Area size of recharge well	Whether functional	Adapted	Remarks
1.	Govt	yes	7	4 x 4 x 2.8 m x 2.10 m 2 x 1.5 x 1.80 m x 2.10 m 1 x 5 x 2 x 2 m 77905	N/A	yes	yes Peristaltic whirp advised

84/5  
 28.2.18  
 NGT/A 217/16

*[Signature]*

VIMAL V. BELANI  
 Asstt. Engineer (C)  
 Delhi Jal Board  
 Delhi

P.R. Gupta  
 Sr. Hydrogeologist  
 Inspector (Scientist-D)  
 H. QWB, SDO, Delhi

*[Signature]*

Principal  
 Sant Nirankari Boys Sr. Sec. School  
 Sant Nirankari Colony, Delhi-9

*[Signature]*  
 Chairman  
 Sant Nirankari Boys Sr. Sec. School  
 Sant Nirankari Colony, Delhi-9